



# GWCC Back of Building





# Back Side Bldg - Lobby



# Back of A Bldg – Looking at B



# B Building – Hall 3



B Building - Hall 3



# Building – Looking at entrance hall



B Building - looking at B2 - B3 entrance door

# B Building Escalator – main lobby



B Building escalator entrance off main lobby

# B Building – B2/B3 entrance off main lobby



B Building - B2/B3 entrance off main lobby



# B Building – damaged door



B Building - damaged door





# B Building – B3 Hall – facing North



B Building - B3 Hall - facing north



nth Degree

# Connecting Concourse – B going A



Connecting Concourse between B Building going to A Building

# Back of A Building - concourse



# Back of A Building - concourse



# Back of A-3 – from concourse



Back of A-3 from concourse

# Connecting Concourse





## A Bldg roof damage (Hinman Dental inside)



# Outside Damage



Outside damage



# Outside Damage





# Omni Hotel damage



# Omni Hotel damage



# Outside Damage





# Omni Hotel

